

Common Causes of Dangerous Air Restriction

- Normal Lint Accumulation in the Dryer Duct
- Kinked or Crushed Exhaust Hose
- Blockage of Termination Hoods



**Even When You Clean the Screen
Lint Still Builds Up in
Every Duct System**

The LintAlert provides peace of mind by identifying sudden changes in airflow. Any accumulation inside the dryer is also hazardous. Remember to have your dryer cleaned periodically.




Protect Your Home & Family

Help Prevent Dryer Fires



For optimal performance, the LintAlert® needs to be installed when the exhaust system is in a clean, or like-new condition.



Have us Install Your LintAlert Today!

LINTALERT® Dryer Safety Alarm



Detect Exhaust Problems






Help Save Energy

Reduce Fire Danger

Keep Your Dryer Exhaust Safe and Efficient

With every load, your LintAlert® checks the exhaust environment and gives you important information so you can help save energy and improve home safety.

LED Indicator Key

-  Normal exhaust pressure (system clean with a recent calibration).
-  Approximately 20 percent blocked.
-  Approximately 32 percent blocked.
-  Approximately 45 percent blocked.
-  Exhaust system is approximately 60 percent blocked and requires maintenance. This critical state is accompanied by an audible alarm which can be muted.



Dryers Cause Over 15,500 Fires Every Year

—Source: U.S. Fire Administration



**Protect Your Home
And Family**

Note: Works on all dryers except those with dual motor technology and dryers that share exhaust systems as occasionally found in high-rises.

Worried About Dryer Fires?

Are your clothes
very hot after a cycle?

Experiencing
Longer Dryer Times?

Home Safety Concerns?

Want Peace of Mind?

Looking to Increase Dryer
Efficiency, Save Money?

Like to Prolong the Life of
Your Dryer and Clothes?



Always Know Your Dryer is Safe and Efficient

Critical Home Safety Issue

Lint makes it past the filter and collects in every dryer's exhaust system. The result is longer dryer times that waste energy and wear out clothes. Most importantly, exhaust problems also create a very real fire danger. Today, you can help save energy and live a safer life.

LintAlert® Protection

The LintAlert should be added as part of every home safety plan. As lint naturally builds up over time, LED indicators progressively illuminate to show how efficiently the dryer is exhausting. When airflow restriction becomes dangerous, an alarm is triggered.